

Amel ford .-

Affidavit

N.S. GOSHOPPINE

महिन्दात वाक्स्ने बंदन

कारणासाती वर्णना ज्यांक वादी केला त्यांनी।

I Mrs. Meghali Deepak Nargacche, Age - 41, Occupation :- Service Address- Jaysingpur Tal. Shirol Dist.- Kolhapur,I am Going to affidavit that

I have Knowledge of both English and Marathi language. I can read and write both of these languages.

I have personally translated all the Marathi documents mentioned below in to English. My educational No. of Corrections on this page.



- 1) 1950 Registration Certificate
- 2) 1860 Registration Certificate
- 3) Fire Certificate
- 4) Recognition Certificate
- 5)NOC Gov. Of Maharashtra
- 6) Deputy Director Permission
- 7) Building Safety Certificate

If Above matter is wrong and illegal I will be liable to prosecute under section 199 and 200 of Indian Pinal Code 1860.

Solemnly affirmed before me

Shrintis Meghali Despok Margacche

Age 41 Occ Service

Rio Taysagental Shiral

Dist Kalhapur

who is identified before me by

whom I personally know
Date - 30 / 05 / 2022

Kagawade Rajesh Baburao Advocate & Notary Public of Govt. of India, Reg. No. 15808/2019

No. of Corrections

CL PERSON

AT SERIAL NO. 387

DATE 30 05 2027









महाराष्ट्र शासन

कार्यकारी अभियंता, सार्वजनिक बांधकाम विभाग, मिरज किल्ला भाग, प्रांत ऑफिस समोर, मिरज जि.सांगली -४१६४१०



दृरध्वनी क्र. (०२३३) २२२२६६५

Email ID :. miraj.ee@mahapwd.com

जा.क्र.साबांविमि/इमारती/ 32(13)

दिनांक :-

1 9 APR 2022!

प्रति.

झिल इंटरनॅशनल स्कूल कवलापूर रोड, बामणोली

विषय :-

इमारत Stability (Safety) प्रमाणपत्र मिळणेबाबत.

15055

संदर्भ:-

सहाय्यक कार्यकारी अभियंता श्रेणी-१, सा.बां.उपविभाग,सांगली यांचे कडील पत्र जा.क्रं.वि.शाखा/४५९/२०२२ दि-०४/०४/२०२२

उपरोक्त विषयास अनुसरून झिल इंटरनॅशनल स्कूल कवलापूर रोड बामणोलो इमारतीचे आक्रीतिए (Safety) प्रमाणपत्र मिळणेबावत मागणी केली होती. त्यास अनुसरून संदर्भिय पत्रान्यये सदर स्कूल इमारतीची पाहणी करून तसा अहवाल या कार्यालयास सादर केला आहे. सदर अहवाल मध्ये खालील प्रमाणे मुद्दो घेतलेली आहेत. तरी ते मुद्दो आपण आपलेस्तरावर पुणं करणेत यावे, मुद्दो खालील प्रमाणे आहेत.

१.इमारतीच्या तळमजल्यावर संपुर्ण इमारतीची माहिती असलेला व आणीवाणीच्या प्रसंगी इमारती मधून सुरक्षितपणे बाहेर पडणेसाठीचा सविस्तर नकाशा लावणेत यावा.

- २.शाळेच्या बसेससाठी स्वतंत्र पार्कींगची सोय करणेत यावी.
- ३. इमारतीच्या सभोवतालचा रस्ता अग्निशमन गाड्यांच्या वाहतुकीसाठी खुला व सुस्थितीत ठेवणेत यावा.

तरी बरील अटींची पुर्तता करणेच्या अधिन राहून सोबत Stability (Safety) प्रमाणपत्र सादर करणेत येत आहे. हे आपले माहितीसाठी सादर.

> कार्यकारी अभियंता सार्वजनिक बांधकाम विभाग,मिरज

प्रत:- सहाय्यक कार्यकारी अभियंता वर्ग-१ सा.बां.उपविभाग,साँगली यांना माहितीसाठी व पुढील कार्यवाहीसाठी सादर

Principal

Manager, Zeal International School

Bannoll, Sang 416 436.

प्रमाणपत्र

प्रमाणित करणेत येते की, बामणोली येथील झिल इंटरनॅशनल स्कुल इमारतीचे बांधकाम सन २०१७साली झालेले असून सदरची इमारत तळमजला (पार्कींग) + चार मजले अशा स्वरुपाची आहे. प्रत्यक्ष पाहणी केली असता सदर इमारत आज रोजी सुस्थितीत व सुरक्षित असल्याचे निदर्शनास आले.

सहायक कार्यकारी अभियंता वर्ग-१, सार्वजनिक बांधकाम उपविभाग, सांगली. कार्यकारी अभियंता सार्वजनिक बांधकाम विभाग, मिरज.

Principal
Zeal Internatio 1 School
Bamnoli, Sangh 416 436.

Manager,

Zeal International School

Managor,
Zeal International School
Bamnoli,Sangli-416 436.

Principal

English Translated Copy

Government of Maharashtra

Executive Engineer, Public Works Department, Miraj
Fort area, in front of Provincial Office, Miraj Dist. Sangli – 416410

Telephone no. (0233) 2222665

Email ID: miraj.ee@mahapwd.com

Out. No. pwdm/Building / 3273/2022

Date - 19/04/ 20221

To.

Zill International School,

Kavalapur Road,

Bamnoli.

Subject :- Building Stability (Safety) Certificate.

Ref :- Assistant Executive Engineer Category-1. Pwd div. letter Letter from Sub-Division, Sangli Vs. Branch / 459/2022 dt-04/04/2022

In accordance with the above subject, demand was made to get the Stability (Safety) Certificate of Zeal International School Kavalapur Road Bamnoli building. Accordingly, the school building has been inspected and a report has been submitted to this office. The following points are taken up in this report. However, we have to complete those issues at our level, the issues are as follows.

- On the ground floor of the building, a detailed map of the entire building should be made to know and to get out of the building safely in case of emergency.
- 2) Separate parking should be provided for school buses.
- The road around the building should be kept open and in good condition for fire trucks.

However, subject to fulfillment of the above conditions, a certificate of Stability (Safety) is being submitted along with it.

This is for your information. :- Assistant Executive Engineer Class-1 Submission to Sub-Division, Sangli for information and further action

-----///-------

Executive Engineer Public Works Department, Miraj The certificate certifies that the Zeal International School building at Bamnoli was constructed in the year 2017 and the building has a ground floor (parking) + four storey's. A physical inspection revealed that the building is in good condition and safe today.

14808/2019 d up to 12-2024

> Assistant Executive Engineer Class-I, Public Works Sub-Division, Sangli.

Executive Engineer, Public Works Department, Miraj.

-----///-----